

taking
PPE

OFF



(CAPR)

OUTSIDE ROOM

1 of 2

TERMINAL DOFFING

Next patient: **NOT COVID+**

Lens Cuff

After coveralls and outer glove removal...

1 **Sanitize** gloves

2 **Place** first wipe on table.

3 **Grab** lens cuff at the left and right side attachments. **Remove** and by pulling outward and forward.

4 **Place** lens cuff on wipe.

5 **Wipe** front and back of lens cuff. **Allow** to dry.

6 **Store** lens cuff in a gallon sized bag labeled with your name.

Helmet

7 **Sanitize** gloves.

8 **Place** second wipe on table.

9 Grasp outer-shell of helmet and **take off**. **Ensure** that the helmet cord doesn't touch your body.

10 **Place** helmet on first wipe.

11 **Sanitize** gloves.

12 **Wipe** inside of the helmet.

13 **Sanitize** gloves.

14 Hold inside of the helmet and **flip** onto second wipe.

15 **Wipe** outside of the helmet.

taking
PPE

OFF



(CAPR)

OUTSIDE ROOM 2 of 2 TERMINAL DOFFING

Next patient: **NOT COVID+**

Battery

16



Sanitize
gloves.

17



Wipe helmet
cord.

18



Sanitize
gloves.

19



Remove and
wipe battery.

20



Sanitize
gloves.

21



Remove belt
and **wipe**.

Exit

22



Sanitize
gloves.

23



Remove
gloves.

24



Wash
hands.