N95 User Seal Check



Important notes



With any N95, you should always **perform a seal check** each time it is donned. **Follow** the manufacturer's manual for best practice.

Each time, Every time. Your Safety Depends on it.



Positive pressure user seal check



Exhale gently while blocking the paths for air to exit the face piece.






Ensure that the face piece is slightly pressurized before pressure causes outward leakage.

Negative pressure user seal check



Inhale sharply while blocking the paths for air to enter the face piece.





Ensure that the face piece collapses slightly under negative pressure that is created with this procedure.

If you can't achieve a proper seal...



If the air leaks out between your face and the respirator, the respirator does not fit your face properly.



DO NOT ENTER a hazardous area.



Readjust the respirator and check the seal again.



If you are still unable to get a good seal, **talk** to your supervisor for a new N95.



